



Existing Condition

1. 6' sidewalks.
2. 5' bike lanes.
3. 4-leg crosswalks incomplete
4. No pedestrian-oriented lighting

5. Chain link fence
6. Weeds and gravel next to sidewalk
7. Underpass and column paint needs updating
8. Large curb radius



Concept Improvements

1. Sidewalks widened to 10'.
2. Bike lane widened to 7'.
3. Crosswalks provided on all four intersection legs per Fruitvale Alive Community Transportation Plan.
4. Pedestrian-oriented lights improve pedestrian safety and match Fruitvale Alive lights.

5. Chain link fence replaced with decorative fencing and relocated to back of columns.
6. Cobble surfacing provides low maintenance edge band.
7. Underpass improvements cleaned and refurbished.
8. Curb radius reduced to shorten pedestrian crossing distance.
9. Gateway signage added to underpass.

I-880 Underpass