



Existing Condition

1. Median narrow and concrete.
2. Roadway wider than needed.
3. 6' sidewalk.
4. Large curb radius.

5. Bus stops unimproved.
6. City-owned area needs improvement.
7. Auto-oriented street lights.
8. Standard bike lanes.



A - Renovated Median

1. Median widened slightly and planted with trees and shrubs.
2. Roadway narrowed slightly to shorten pedestrian crossing distance.
3. Sidewalk widened to 10' and planted with street trees.
4. Curb radius reduced to shorten pedestrian crossing distance.

5. Bus stops improved.
6. City-owned area landscaped and improved.
7. Pedestrian- and auto-oriented street lights.
8. Bike lanes widened and buffered with paint stripe.
9. New gateway sign.



B - Widened Median

1. Median widened and planted with trees and shrubs.
2. Roadway narrowed to shorten pedestrian crossing distance.
3. Sidewalk widened to 10' and planted with street trees.
4. Curb radius reduced to shorten pedestrian crossing distance.

5. Bus stops improved.
6. City-owned area landscaped and improved.
7. Pedestrian- and auto-oriented street lights.
8. Bike lanes widened and buffered with paint stripe.
9. Salvaged Hegenberger Road gateway sign with new banner.

Alameda Avenue Intersection / Gateway to Oakland